

RECEIVED
Office of Oil and Gas

MAR 19 2014

WV Department of
Environmental Protection

DANNY WEBB CONSTRUCTION CO., INC.

PHONE: 304-465-9448 FAX: 304-465-9448 P.O. Box 267 Lochgelly, WV 25866

Annual Pipeline Integrity Test

January 17, 2014

Pressured pipe lines between storage tanks and well head to 900 lbs. let stand 1hr. No leaks or problems were detected.

Overall condition of facility: Needs additional housekeeping.

By



President

RECEIVED
Office of Oil and Gas

MAR 19 2014

WV Department of
Environmental Protection

DANNY WEBB CONSTRUCTION CO., INC.

PHONE: 304-465-9448 FAX: 304-465-9448 P.O. Box 267 Lochgelly, WV 25866

Annual Pipeline Integrity Test

January 29, 2013

Pressured pipe lines between storage tanks and well head to 900 lbs. let stand 1hr. No leaks or problems were detected.

Overall condition of facility: Needs additional housekeeping.

By



President

RECEIVED
Office of Oil and Gas

MAR 19 2014

WV Department of
Environmental Protection

DANNY WEBB CONSTRUCTION CO., INC.

PHONE: 304-465-9448 FAX: 304-465-9448 P.O. Box 267 Lochgelly, WV 25866

Annual Pipeline Integrity Test

January 26, 2012

Pressured pipe lines between storage tanks and well head to 900 lbs. let stand 1hr. No leaks or problems were detected.

Overall condition of facility: No problems were found, needs additional housekeeping.

By



President

RECEIVED
Office of Oil and Gas

MAR 19 2014

WV Department of
Environmental Protection

DANNY WEBB CONSTRUCTION CO., INC.

PHONE: 304-465-9448 FAX: 304-465-9448 P.O. Box 267 Lochgelly, WV 25866

Annual Pipeline Integrity Test

January 6, 2011

Pressured pipe lines between storage tanks and well head to 900 lbs. let stand 1hr. No leaks or problems were detected.

Overall condition of facility: No problems were found.

By



President

RECEIVED
Office of Oil and Gas

MAR 19 2014

DANNY WEBB CONSTRUCTION CO., INC.

WV Department of
Environmental Protection

PHONE: 304-465-9448 FAX: 304-465-9448 P.O. Box 267 Lochgelly, WV 25866


Annual Pipeline Integrity Test

January 11, 2010

Pressured pipe lines between storage tanks and well head to 900 lbs. let stand 1hr. No leaks or problems were detected.

Overall condition of facility: No problems except additional housekeeping.

By



President