



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street
Charleston, WV 25304
(304) 926-0450 fax (304) 926-0452

Earl Ray Tomblin, Governor
Randy C. Huffman, Cabinet Secretary
www.dep.wv.gov

September 20, 2013

DEP/OOG Investigation: George Monk Gas Well Study 2012

Site API# 39-01046

- Arrived at location on April 5, 2013
- Location looked to be in compliance
- No issues with access road or well site

Site API#39-1168

- Arrived at location on April 30, 2013
- Location looked to be in compliance
- Well in in production with meter set on location
- Company has worked access roads
- API Number is correct

Site API#39-01198

- Arrived at location on April 30, 2013.
- Location looked to be in compliance
- No issues with access road or well site

Site API# 39-01552

- Arrived at location on April 25, 2013
- Site well maintained and in compliance
- No problems encountered at site

Site API#39-02306

- Arrived at location on April 25, 2013
- Well is Plugged
- No problems encountered at site – in compliance

Promoting a healthy environment.

Site API#39-02319

- Arrived at location on April 25, 2013
- Well is Plugged
- No problems encountered at site

CRANBERRY TANK- Arrived at location on April 5, 2013

This tank is a double wall tank and does not require additional secondary containment

ABANDONED TANK- Arrived at location on April 5, 2013

This is an empty spare tank on the site at the well location 39-2204.

Site API#79-00615

- Arrived on location on June 24, 2013
- Well is abandoned
- Site looked good with grass / vegetation growing – in compliance.
- Double walled tank looked o.k.

Site API#79-00702

- Arrived at location on July 10 8, 2013
- Double walled tank with tank dike.
- Site looked good with grass / vegetation growing

Site API#79-00731

- Arrived on location on June 25, 2013
- Secondary containment but needs improvement / operator to repair.
- Some trash on location that operator stated they would remove.
- Company will work access road & paint well

Site API#79-1288

- Arrived on location on June 26, 2013
- Access road in good shape, no evidence of runoff /erosion
- Drains in good condition
- Area has good vegetation

Site API#79-01299

- Arrived on location on June 20, 2013
- Access road in good shape, no evidence of runoff /erosion
- Drains in good condition
- Area has good vegetation

Site API#79-01314

- Arrived on location on June 25, 2013
- Access road in good shape, no evidence of runoff /erosion
- Drains in good condition
- Area has good vegetation

Site API#79-01492

- Arrived on location on June 20, 2013
- Access road in good shape, no evidence of runoff /erosion
- Drains in good condition
- Area has good vegetation

Site API#97-03707

- Arrived on location on May 7, 2013
- There are no maintenance or trash issues at this site
- Drains are in good condition. Drainage /sediment control devices in place by order of EPA
- Area has good vegetation

Site API#79-3708

- Arrived on location on May 7, 2013
- There are no maintenance or trash issues at this site
- Drains are in good condition. Drainage /sediment control devices in place by order of EPA
- Area has good vegetation

Site API#79-03716

- Arrived on location on May 7, 2013
- Well was lost and plugged in May 2011, replacement well was to be permitted and drilled on same site.
- To reclaim and rebuild pits would create more environmental impact than to leave them open for the replacement well.
- The well was plugged and a swedge was put on the 7" casing to protect the threads until the monument could be set in place. Monument was set in place sometime after Monk photo was taken.
- There are no maintenance, drainage, or sediment control issues at this site – in compliance.