

INSPECTORS REPORT

Operator: Synergy
API Number: 39-2803

Findings:

No Activity no PSI on well or
ANNULUS. Well painted up looking for permit
to be issued

Does this inspection identify any dust issues? Yes No. If Yes, explain.

Angelo Miller
Oil & Gas Inspector

10-23-19
Date