

COMPLETE WELL INSPECTION FORM

ASSIGNED API NUMBER 47- \_\_\_\_\_  
API NUMBER 47- 109-02032 \_\_\_\_\_  
FARM NAME Gilbert & Plumley \_\_\_\_\_

GPS DATE 6/26/2014  
WELL OPERATOR GeoMet Operating Co., Inc.  
WELL NUMBER A-55 SWD (UIC)

A. THE ACCESS ROAD MEETS ALL REQUIREMENTS? (22-6-30, 35CSR-4-16)

- 1. CULVERTS PROPERLY SIZED AND SPACED  YES  NO  N/A
- 2. DISSIPATING DEVICES  YES  NO  N/A
- 3. PROPERLY MAINTAINED  YES  NO  N/A
- 4. DIVERSION DITCHES IN PLACE  YES  NO  N/A

B. THE WELL AND LOCATION ARE PROPERLY EQUIPPED AND RECLAIMED? (22-6-30, 22-6-6, 35CSR-4-16)

- 1. API NUMBER  YES  NO  N/A
- 2. DIVERSION DITCHES  YES  NO  N/A
- 3. ALL DISTURBED AREAS RECLAIMED  YES  NO  N/A
- 4. IS SITE FREE OF OIL, GAS AND SALT WATER LEAKS  YES  NO  N/A
- 5. IS WELL PRODUCING  YES  NO  N/A
- 6. PRODUCTION REPORTS BEEN FILED  YES  NO  N/A

C. DOES THE SPILL PREVENTION MEET ALL REQUIREMENTS?(22-6-7, 35CSR1-7, 35CSR-4-11 TO 17)

- 1. ARE TANKS PROPERLY EQUIPPED WITH THE FOLLOWING:
  - A. SECONDARY CONTAINMENT  YES  NO  N/A
  - B. VALVES  YES  NO  N/A
  - C. EQUALIZING LINES  YES  NO  N/A
- 2. ARE SECONDARY CONTAINMENT STRUCTURES PROPERLY CONSTRUCTED:
  - A. IMPERVIOUS  YES  NO  N/A
  - B. DIKES PROPERLY SIZED  YES  NO  N/A
  - C. SURFACE WATER PROPERLY DRAINED  YES  NO  N/A
  - D. VALVES INSTALLED ON DIKE DRAINS  YES  NO  N/A
  - E. DIKE DRAIN VALVES CLOSED  YES  NO  N/A

D. IS SALT WATER BEING PROPERLY DISPOSED OF? (22-6-7)  YES  NO  N/A

E. WAS THIS INSPECTION ROUTINE?  YES  NO  
SPECIFY (COMPLAINT, RANDOM, ETC.) \_\_\_\_\_

F. IS THIS WELL PART OF A SECONDARY RECOVERY FIELD? YES  NO

G. WERE ENFORCEMENT ACTIONS TAKEN AS A RESULT OF THIS INSPECTION? YES  NO  
SPECIFY (VIOLATION, WARNING LETTER) \_\_\_\_\_

COMMENTS: Lat 37.5090440 Long 81.7028469 \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

DATE 6/26/2014 INSPECTOR Ross Eller

Received  
Office of Oil & Gas  
JUL 02 2014